**D**ata Page 1 of 8

**S**heet

# 1. PRODUCT AND COMPANY IDENTIFICATION:

PRODUCT NAME: Cast Iron Welding Rod "Nomacast"

FORNEY SKUs: 43401

**MANUFACTURER:** Forney Industries, Inc.

2057 Vermont Drive

Fort Collins, CO 80525 U.S.A.

Phone: 800-521-6038 Fax: 970-498-9505

E-mail: customerservice@forneyind.com

**EMERGENCY TELEPHONE NUMBER**: 800-535-5053

# 2. HAZARD IDENTIFICATION:

**Emergency Overview:** This product is normally not considered hazardous as shipped. Avoid eye contact or inhalation of dust from the product. When this product is used in a welding process, the most important hazards are welding fumes, heat, radiation and electric shock.

Classification of the Substance/Mixture

CLP/GHS Classification (1272/2008):

Skin Irritation, Category 2 Eye Irritation, Category 2A

Specific Target Organ Toxicity (Single Exposure), Category 3

EU Classification (67/548/EEC):

Irritant (Xi), R36/37/38

Hazardous Classification per 29CFR 1910.1200 (Rev. July 1, 2012):

Skin Irritation, Category 2 Eye Irritation, Category 2A

Specific Target Organ Toxicity (Single Exposure), Category 3

Labelling:

Symbols:



Signal Word: Warning Hazard Statements:

H315 - Causes skin irritation.

H319 – Causes serious eye irritation.H335 – May cause respiratory irritation.

**Precautionary Statements:** 

P261 – Avoid breathing dust/fume/gas/mist/vapours/spray.

P264 - Wash skin and hair thoroughly after handling.

P271 – Use only outdoors or in well-ventilated area.

**P280** – Wear protective gloves/eye protection/face protection.

P302+P352 - IF ON SKIN: Wash with plenty of soap and water.

P304+P340 – IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing.

P305+P351+P358 – IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.

P312 - Call a POISON CENTER or doctor/physician if you feel unwell.

**D**ata Page 2 of 8

**S**heet

P332+P313 – IF skin irritation occurs: Get medical advice/attention.

P337+P313 – IF eye irritation persists: Get medical advice/attention.

P362 – Take off contaminated clothing and wash before reuse.

P403+P233 – Store in well-ventilated place. Keep container tightly closed.

P405 - Store locked up.

**P501 –** Dispose of contents/container in accordance with local/regional/national/international regulations.

#### 3 COMPOSITION / INFORMATION ON INGREDIENTS:

3. CUMPUS		FURIVI	ATION ON INC	SKEDICINI 3				
Chemical Identity	CAS#	Range %	OSHA PEL (mg/m3)	ACGIH-TLV (mg/m3)	Carcinogenicity	EU Classification (67/548/EEC)	CLP/GHS Classification (1272/2008)	Hazardous Classification per 29CFR 1910.1200 (Rev. July, 2012)
Calcium Carbonate	1317-65-3	1-11	5 (as CaO)	10	No	Not Dangerous	Not Hazardous	Not Hazardous
Calcium Fluoride	7789-75-5	1-11	2.5 ( as F )	2.5 (as F)	No	(Xi) R36/37/38	(H315) Skin Irrit 2 (H319) Eye Irrit 2A (H335) STOT SE 3 (H335)	(H315) Skin Irrit 2 (H319) Eye Irrit 2A (H335) STOT SE 3 (H335) STOT SE
Graphite	7782-42-5	1-11	15 (Total Dust)	2	No	X(Xi) R36/37	(H319) Eye Irrit 2A (H335) STOT SE 3 (H335) STOT	(H319) Eye Irrit 2A (1) (H335) STOT SE 3 (1)
Barium Carbonate	513-77-9	5-15	0.5	0.5	No	(Xn) R22	(H302) Acute Tox. 4 🕩	(H302) Acute Tox. 4 🕩
Strontium Carbonate	1633-05-2	1-11	15	10	No	Not Dangerous	Not Hazardous	Not Hazardous
#Manganese	7439-96-5	1-11	5	1	No	(Xn) R48	(H373) STOT RE 2 �	(H373) STOT RE 2 �
Iron	7439-89-6	60-70	10 ( as Fe2O3 )	5 (as Fe2O3)	No	Not Dangerous	Not Hazardous	Not Hazardous
Sodium Silicate	1344-09-8	1-11	NR	5	No	(C) R34 (Xi) R37	(H314) Skin Corr. 1B (H335) STOT SE 3 (1)	(H314) Skin Corr. 1B �� (H335) STOT SE 3 ��

Important This section covers the materials of which the products manufactured. The fumes and gases produced during normal use of this product are covered in section 10. The term "Hazardous" in "Hazardous Material" should be interpreted as a term required and defined in OSHA Hazard Communication Standard 29CFR 1910-1200 and it does not necessarily imply the existence of hazard. The chemicals or compounds reportable by Section 313 of SARA are marked by the symbol #.

#### 4. FIRST AID MEASURES:

**Inhalation**: Remove to fresh air immediately or administer oxygen. Get medical attention immediately. **Skin**: Flush skin with large amounts of water. If irritation develops and persists, get medical attention.

**Eye:** Flush eyes with water for at least 15 minutes. Get medical attention.

**Ingestion**: Obtain medical attention immediately if ingested.

**Electric Shock:** Disconnect and turn off the power. Use a nonconductive material to pull victim away from contact with live parts or wires. Immediately contact a physician.

## 5. FIRE-FIGHTING MEASURES:

**Suitable Extinguishing Media:** Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Welding arcs and sparks can ignite combustible and flammable materials. Use the extinguishing media recommended for the burning material and fire situation.

**Unsuitable Extinguishing Media:** Do not use water on molten metal. Large fires may be flooded with water from a distance.

**D**ata Page 3 of 8

**S**heet

**Specific Hazards Arising From Chemical:** Keep away from heat/spark/open flames/hot surfaces – No smoking. Use explosion-proof electrical/ventilating/lighting/equipment. Keep away from any possible contact with water, because of violent reaction and possible flash fire. Brush off particles from skin and immerse in cool water/wrap in wet bandage.

Manganese/Manganese Oxides, Iron Oxides, Hydrogen fluoride, Calcium oxide, Carbon oxides, Barium oxides, Iron oxides, Sodium oxides, Silicon oxide,

**Protective Equipment:** Fire fighters should wear complete protective clothing including self-contained breathing apparatus.

# 6. ACCIDENTAL RELEASE MEASURES:

Personal Precautions: Refer to section 8. Environment Precautions: Refer to section 13.

**Cleaning Measures:** Solid objects may be picked up and placed into a container. Liquids or pastes should be scooped up and placed into a container. Wear proper protective equipment while handling these materials. Do not discard as refuse.

\_\_\_\_\_

## 7. HANDLING AND STORAGE:

**Precautions for Safe Handling:** Handle with care to avoid stings or cuts. Wear gloves when handling welding consumables. Avoid exposure to dust. Do not ingest. Some individuals can develop an allergic reaction to certain materials. Retain all warning and identity labels.

**Conditions for Safe Storage:** Store in dry place in closed packages. Keep separate from chemical substances like acids and strong bases, which could cause chemical reactions. Ground/Bond container and receiving equipment.

# 8. EXPOSURE CONTROLS/ PERSONAL PROTECTION:

**Engineering Controls:** Avoid exposure to welding fumes, radiation, spatter, electric shock, heated materials and dust. Ensure sufficient ventilation, local exhaust, or both, to keep welding fumes and gases from breathing zone and general area. Keep work place and protective clothing clean and dry. Train welders to avoid contact with live electrical parts and insulate conductive parts. Check condition of protective clothing and equipment on a regular basis.

**Exposure limits:** Use industrial hygiene equipment to ensure that exposure does not exceed applicable national exposure limits. The limits defined under section 3 can be used as guidance. Unless noted, all values are for 8 hour time weighted average. For information about welding fume analysis refer to section 10.

Biological limits: No available data

Personal protection:

**Respiratory protection:** Use an air purifying dust respirator when welding or brazing in a confined space, or when local exhaust or ventilation is not sufficient to keep exposure values within safe limits.

**Hands protection:** Wear appropriate gloves to prevent skin contact.

#### **EN 12477: Protection gloves for welders**

Type A	Type B
2 (500)	1 (100)
1 (1.2)	1 (1.2)
2 (25)	1 (10)
2 (60)	1 (20)
3	2
1	1
2	-
3	2
1 (11)	4 (6.5)
	2 (500) 1 (1.2) 2 (25) 2 (60) 3 1

**S**afety **D**ata Latest Revision: May 2017

Page 4 of 8

# **S**heet

Type B gloves are recommended when high dexterity is required as for TIG welding, while type A gloves are recommended for other welding processes. The contact temp (°C) is 100 and the threshold time (seconds) >15.

**Eyes protection:** Welder's helmet or face shield with colour absorbing lenses. Shield and filter to provide protection from harmful UV radiation, infra red and molten metal approved to standard EN379. Filter shade to be a minimum of shade 9.

**Skin protection:** Heat-resistant protective clothing. Wear safety boots, apron, arm and shoulder protection. Keep protective clothing clean and dry. Clothing should be selected to suit the level, duration and purpose of the welding activity.

	Class 1
Impact of Spatter	15 Drops
Heat Transfer (radiation)	RHTI 24 ≥ 7 seconds
Process	Manual welding with light formation of spatter and drops     Gas Welding     TIG Welding     MIG Welding     Micro plasma welding     Brazing     Spot Welding     MMA Welding (with rutile-covered electrode)
Environmental Conditions	Operation of machines  Oxygen cutting machines  Plasma cutting machines  Resistance welding machines  Machines for thermal spraying  Bench welding

	Class 2
Impact of Spatter	25 Drops
Heat Transfer (radiation)	RHTI 24 ≥ 16 seconds
Process	Manual welding with heavy formation of spatter and drops  MMA welding (with basic or cellulose-covered electrodes)  MAG welding (with CO2 or mixed gases)  MIG Welding (with high current)  Self shielded flux core arc welding  Plasma cutting  Gouging  Oxygen cutting  Thermal spraying
Environmental	Operation of machines
Conditions	<ul> <li>In confined spaces</li> <li>At overhead welding/cutting or in comparable constrained positions</li> </ul>

# 9. PHYSICAL AND CHEMICAL PROPERTIES:

Appearance: Solid. Color: Black Odour: Odourless

Odour Threshold: Not Available

pH Value: Not Available

Melting Point/Melting Range: 1560 - 2000° F, 850 - 1100° C

Freezing Point: Not Available

**D**ata Page 5 of 8

**S**heet

Boiling Point/Boiling Range: Not Available

Flash point: Not Available

Evaporation Rate: Not Available Self-in flammability: Not Available Explosion limits: Not Available Vapour pressure: Not Available Vapour density: Not Available Density at 20°C: Not Available Relative density: 6-9 g/cm3 Solubility: Insoluble in water.

Partition coefficient: Not Available Auto-ignition temperature: Not Available Decomposition temperature: Not Available

Other Information: No available data.

## 10. STABILITY AND REACTIVITY:

**Chemical Stability:** This product is stable under normal conditions.

**Hazardous Reactions:** Contact with chemical substances like acids or strong bases cause generation of gas.

Conditions to Avoid: Not applicable. Incompatible Materials: Reacts with acid.

**Hazardous Decomposition Products:** When this product is used in a welding process, hazardous decomposition product would include those from volatilization, reaction or oxidation of the material listed in section 3 and those from the base metal and coating. The amount of fumes generated from this product varies with welding parameters and dimensions.

Refer to applicable national exposure limits for fume compounds, including those exposure limits for fume compounds found in section 3. Reasonably expected gaseous products would include carbon oxides, nitrogen oxides and ozone. Air contaminants around the welding area can be affected by the welding process and influence the composition and quality of fumes and gases produced.

## 11. TOXICOLOGICAL INFORMATION:

**Signs and Symptoms of Overexposure:** Inhalation of welding fumes and gases can be dangerous to your health. Classification of welding fumes is difficult because of varying base materials, coatings, air contaminants and processes. The Internal Agency for Research on Cancer has classified welding fumes as possible carcinogenic to humans (Group 2B).

**Acute Effects:** Overexposure to welding fumes may result in symptoms like metal fume fever, dizziness, nausea, dryness or irritation of the nose, throat or eyes. May cause sensitisation by skin contact

LD/LC50 Values that are relevant for classification		
Calcium Car	bonate 1317-65-3	
Oral	LD50	>2000 mg/kg (rat)
Inhalation	LC50	>3 mg/L/4hr. (rat)
Dermal	LD50	>2000 mg/kg (rat)

LD/LC50 Values that are relevant for classification		
Calcium Fluo	oride 7789-75-5	
Oral	LD50	>2000 mg/kg (rat)
Inhalation	LC50	>5070 mg/m3/4 hr. (rat)

**S**afety

Latest Revision: May 2017 **D**ata

Page 6 of 8

# **S**heet

LD/LC50 Val	ues that are relevant fo	r classification
Barium Carb	onate 513-77-9	
Oral	LD50	418 mg/kg (rat)
	LC50	6950 mg/l (96h) (mosquito fish)

LD/LC50 Values that are relevant for classification		
Manganese 7439-96-5		
Oral	LD50	9000 mg/kg (rat)

LD/LC50 Val	LD/LC50 Values that are relevant for classification	
Iron 7439-89	-6	
Oral	LD50	30000 mg/kg (rat)

Chronic Effects: Overexposure to welding fumes may affect pulmonary function and eyes. Overexposure to manganese and manganese compounds above safe exposure limits can cause irreversible damage to the central nervous system, including the brain, symptoms of which may include slurred speech, lethargy, tremor, muscular weakness, psychological disturbances and spastic gait.

#### 12. ECOLOGICAL INFORMATION:

**Toxicity:** Welding rods contain metals which are considered to be very toxic towards aquatic organisms. Finely divided welding rods are therefore considered harmful to aquatic organisms.

**Persistence and Degradability:** The welding rods consist of elements that can not degrade any further in the environment. Bio accumulative Potential: Welding rods contain heavy metals which bio accumulates in the food chain. The following figures are the bio concentration factor (BCF) for the substances on their own.

BCF:

Iron, BCF: 140000 Manganese, BCF: 59052

Mobility in Soil: Welding rods are not soluble in water or soil. Particles formed by working welding rods can be transported in

the air.

Other Adverse Effects: In massive form, welding rods present no hazards to the aquatic environment.

Welding materials could degrade into components originating from the materials used in the welding process. Avoid exposure to conditions that could lead to accumulation in soils or groundwater. Harmful to aquatic organisms, may cause long-term adverse effects in the aquatic environment.

#### 13. DISPOSAL CONSIDERATIONS:

**Product:** For product elimination, consult recycling companies or appropriate local authority.

USA RCRA: In their intended manner of use, this product should not be released into the environment and may cause long lasting harmful effects to aquatic life. Residue from welding consumables and processes could degrade and accumulate in soils and groundwater.

**Package:** May be disposed in approved landfills provided local regulations are observed.

## 14. TRANSPORT INFORMATION:

**UN-number**: Welding rods are not classified as dangerous goods for transport and has no UN number.

UN proper shipping name: Welding rods are not classified as dangerous goods for transport and has no UN proper shipping name.

**Transport hazard class:** Welding rods are not classified as dangerous goods for transport.

Packing group: There are not any special precautions with which a user should or must comply or be aware of in connection with transport or conveyance either within or outside premises.

**D**ata Page 7 of 8

**S**heet

Environmental hazards: Welding rods are not environmentally hazardous according to the criteria of the UN Model Regulations (as reflected in the IMDG Code, ADR, RID and AND) and/or a marine pollutant to the IMDG Code.

**Special precautions for users:** There are not any special precautions which a user should or must comply or be aware of in connection with transport or conveyance either within or outside premises of the welding rod.

Transport in Bulk According to Annex III MARPOL 73/78 and the IBC Code: Welding rods in massive form do not subject under MARPOL 73/78 and the IBC Code. Not applicable – product is transported only in packaged form.

#### 15. REGULATORY INFORMATION:

Safety, health and environment regulations/legislation specific for the substance or mixture: Read and understand the manufacturer's instructions, your employer's safety practices and the health and safety instructions on the label. Observe any federal and local regulations. Take precautions when welding and protect yourself and others.

Warning: Welding fumes and gases are hazardous to your health and may damage lungs and other organs. Use adequate ventilation. Electric shock can kill. Arc rays and sparks can injure eyes and burn skin. Wear correct hand, head, eye and body protection.

Chemical safety assessment: No

USA: Under the OSHA Hazard Communication Standard, this product is considered hazardous.

CALIFORNIA PROPOSITION 65: No compounds present. (California Health & Safety Code § 25249.5 et seg.)

United States EPA Toxic Substance Control Act: All constituents of this product are on the TSCA inventory list or are excluded

#### **EPCRA/SARA Title III Toxic Chemicals**

The following metallic components are listed as SARA 313 "Toxic Chemicals" and potential subject to annual SARA reporting. See Section 3 for weight percentage.

Ingredient Name	Disclosure Threshold
Magnesium	5 mg/m3

#### 16. OTHER INFORMATION:

The information in this document is believed to be correct as of the date issued. However, no warranty is expressed to be implied regarding the accuracy or completeness of this information. This information and product are furnished on the condition that the person receiving them shall make his own determinations as to the suitability of the product for his particular purpose and on the condition that he assumes the risk of his use thereof.

This Material Safety Data Sheet complies with the EC directives 91/155/EEC and 93/112/EEC, including modifications 2001/58/EC.

Complies with OSHA Communication Standard 29 CFR 1910.1200 and Superfund Amendments and Reauthorization Act (SARA) of 1986 Public Law 99-499

## **Hazard Statements:**

H302 – Harmful if swallowed...

**H314** – Causes severe skin burns and eye damage.

H315 – Causes skin irritation.

**H319** – Causes serious eye irritation.

H335 – May cause respiratory irritation.

H373 – May cause damage to organs through prolonged or repeated exposure.

#### **R-Phrases:**

**R22** – Harmful if swallowed.

**R34** – Causes burns.

**R36/37** – Irritating to eyes and respiratory system.

R36/37/38 – Irritating to eyes, respiratory system and skin.

**R37** – Irritating to respiratory system.

R48 – Danger of serious damage to health through prolonged exposure.

**D**ata Page 8 of 8

**S**heet

## **S-Phrases:**

**S22** – Do not breathe dust.

**S24/25** – Avoid contact with skin and eyes.

**S26** – In case of contact with eyes, rinse immediately with plenty of water and seek medical advice.

S36/37/39 – Wear suitable protective clothing, gloves and eye/face protection.

S43 – In case of fire, use fire-fighting equipment on basis class D.

S45 – In case of accident or if you feel unwell, seek medical advice immediately (show the label where possible).

End of the document.