

595

Cove Base Adhesive

For residential or commercial rubber, vinyl and carpet cove base

- White in color
- Aggressive grab - prevents slip during installation
- No open time required
- Excellent wet strength
- Plasticizer migration resistant
- Easy cleanup with water
- Excellent trowelability
- Solvent free



Trowels & Coverage

Recommended trowel sizes are guidelines only and are minimum requirements.



Sawtooth D=1/8", W=1/8", A=1/8"

2 1/2" (63.5 mm) Cove Base

310 - 340 lin. ft. / gal.

25 - 27 lin. M / L

4" (10 cm) Cove Base

220 - 240 lin. ft. / gal.

17.7 - 19.3 lin. M / L

6" (15.24 cm) Cove Base

165 - 180 lin. ft. / gal.

13.2 - 14.5 lin. M / L

Tube Applications

(3) 1/8" / 3.2 mm Beads (Standard for 4" / 10 cm Cove Base)

50 lin. ft. (15.24 lin. M) per 30 oz. cartridge

The W.W. Henry Company
400 Ardex Park Drive
Aliquippa, PA 15001
(724)203-8000
1-800-232-4832
www.wwhenry.com

HENRY® 595

Cove Base Adhesive

Description

HENRY® 595 Cove Base Adhesive is a high-performance, solvent-free, white adhesive used in the installation of rubber, vinyl and carpet cove base.

Use For

Rubber, vinyl and carpet cove base.

Bonds To

Refer to the cove base manufacturer for acceptable substrates.

HENRY 595 bonds to concrete, concrete block, gypsum drywall, plaster, wood, plywood, brick, plastic laminate and mechanically abraded metal on all grade levels. Surfaces must be structurally sound, clean, smooth and dry.

Preparation

Refer to the cove base manufacturer's specific recommendations.

Acclimate the installation area, adhesive and cove base in an enclosed building at a minimum of 65°F (18°C) for at least 48 hours before, during and for 48 hours after installation.

Substrate must be sound, smooth and flat in accordance with the cove base manufacturer's recommendations. Ensure that the substrate is solid and securely fixed to provide a rigid base free of undue flex. All loose boards and panels must be re-nailed to create a sound surface.

Substrate must be clean, dry and free of excess moisture and alkali. Mechanically remove dirt, wax, grease, paints, oils, sealers, curing compounds and all foreign matter that would interfere with proper adhesion. Fill all cracks, holes and low spots.

Glazed or metal surfaces must be roughened mechanically.

Installation

Follow the cove base manufacturer's guidelines for layout and design.

11 oz. or 30 oz. tube

Apply with a standard closed-barrel gun or open-barrel skeleton gun.

Closed barrel gun: Cut spout about 1/2" (12.7 mm) from top of tube. Puncture inner seal. Insert cartridge, and attach nozzle.

Skeleton gun: Cut spout near tip to produce 1/8" (3.2 mm) bead. Puncture inner seal, and insert cartridge. Use two beads for 2 1/2" / 63.55 mm cove base, three beads for 4" / 10 cm cove base and five beads for 6" / 15.24 cm cove base.

1 Gallon or 4 Gallon Pail

Use recommended trowel to spread adhesive to the back of the cove base or directly to the substrate.

Leave a 1/8" (3.2 mm) clearance at the top of the cove base to prevent adhesive oozing.

Set cove base immediately into wet adhesive. Press firmly to the wall, rubbing across the face of the cove base with a soft cloth. To ensure a tight fit, rub toward previously installed section.

Do not allow a heavy film to form on the surface of the adhesive. If the adhesive dries or skins over, it must be scraped up, and fresh adhesive needs to be applied.

Cleanup

Remove wet adhesive residue with a clean, white cloth dampened with soapy water. Use mineral spirits for dried adhesive residue. When using mineral spirits, carefully follow the recommendations of the manufacturer, and test a small area before proceeding to make sure it does not damage the surface being cleaned.

Warranty

10-Year Limited HENRY'S BEST WARRANTY. Failure to follow written directions will void the warranty. For complete warranty details, please contact our Customer Service Center at (800) 232-4832.

Notes

Do not reuse container. Dispose of container and adhesive residue in accordance with federal, state and local waste disposal regulations. Do not flush adhesive down drains.

- FOR PROFESSIONAL USE ONLY
- Freeze/thaw stable to 10°F (-12°C). Avoid lower temperatures or multiple freeze/thaw cycles
- Shelf life is 1 year, if unopened
- VOC: 0 g/L

Precautions

Carefully read and follow all precautions and warnings on the product label. For complete safety information, please refer to the Material Safety Data Sheet (MSDS) available at www.wwhenry.com.

MADE IN THE U.S.A.
The W.W. Henry Company
400 Ardex Park Drive
Aliquippa, PA 15001
www.wwhenry.com

© 2013 W.W. HENRY, L.P. All rights reserved.
03-20-2013