

Latex Barn and Fence Paint



Product Description

Valspar Latex Barn and Fence Paint is made with selected materials to provide protection on exterior wood and metal surfaces. It flows on smoothly and dries to a tough, durable finish. Fade and weather resistant too.

Features

• Fade and Weather Resistant

Recommended Uses

- Barns
- Fences
- Sheds
- Silos
- Factories
- General exterior surfaces

Colors and Part Numbers

	Part Number
Red	3121-10 (Gallon)
	3125-70 (5 Gallon)
White	3121-70 (Gallon)
	3125-70 (5 Gallon)

Typical Properties (18-3121-70 Series)

Vehicle Type: Acrylic Copolymer

Sheen: 5 Units @ 60° angle

Solids by Volume: 32%

Solids by Weight: 49%

Weight per Gallon: 11.6 lbs./gal.

VOC: Less than 50 g/L

Viscosity: 82-88 Krebs Units

Dry Time: 77°F @ 50% Relative Humidity

To the touch: 20 minute(s)

Recoat: 4 hour(s)

Washing: Allow at least 7 days before washing.

Use mild detergent and sponge.

Full Cure: 7 day(s)

Surface Coverage: 400 sq. ft./gal.

At: 4.0 mil Wet, 1.2 mil Dry

Storage and Disposal

- Do not freeze.
- Keep container closed when not in use.
- Do not transfer contents to other containers for storage or disposal.
- In case of spillage, absorb with inert material such as sand or kitty litter.
- Dispose of contaminated absorbent, container and/or unused contents in accordance with local, state and federal regulations.
- DANGER: Rags, steel wool or waste soaked with this product may spontaneously catch fire if improperly discarded. Immediately after each use, place rags, steel wool or waste in a sealed, water-filled metal container.

Shipping and Packaging

Freight Classification: Paint or Paint Related

Material. Protect from freezing.

Packaging: Gallons – 4 per carton

5 Gallon Pails

Surface Preparation

Read the Lead Warning in Cautions section. Clean surface thoroughly. Remove dirt and grease with allpurpose cleaner. Wash dirt from protected areas, such as under eaves. Remove loose or peeling paint and rust with a wire brush and scraper. Dull glossy areas with gloss remover, sandpaper or steel wool. Caulk cracks and crevices around windows, doors and trim. Unpainted wood or badly weathered surfaces should be primed with a first coat of Valspar Latex Barn & Fence Paint thinned with one pint of water per gallon of paint. For metal roofs, tin or iron surfaces, gutters and downspouts, be sure surface is clean. Remove all loose paint, rust and scale before painting. Prime with metal primer. Do not paint in hot sunlight. Clean mildew from the surface: Where high temperature and humidity are common, mildew can be a problem. Mildew is a fungus growth that looks like dirt, but detergent will not wash it off. If you see mildew, or if you do not see any but know it is a problem in your area, scrub surface before painting with a commercial mildew remover or 1 part liquid chlorine bleach to 3 parts water. Avoid skin or eye contact when working with bleach solution. Rinse thoroughly.

Application and Clean-up

Paint only when surface and air temperatures are above 50 °F (10 °C). Stir paint thoroughly before and while painting. Do not paint in damp weather. Start painting at the highest point and work from left to right. Paint the gutters and downspouts, then the windows and frames. To prevent sticking, move windows up and down after 20 minutes. Next, do the siding. Brush paint well into surface. Always finish up at a door, window or outer edge. Do not stop painting in the middle of an open space. Thin sparingly, if necessary, with water. Clean brushes, rollers, equipment and hands with warm soap and water.

Cautions (*18-3121-70 Series*)

WARNING: May cause eye and skin irritation. Avoid breathing vapors or spray mist. If painting indoors, open windows and doors or use other means to ensure fresh air entry during application and drying. If you experience eye watering, headache or dizziness or if air monitoring demonstrates vapor/mist levels above applicable limits, wear an appropriate, properly fitted respirator (NIOSH approved) during and after application. Follow respirator manufacturer's direction for respirator use. AVOID CONTACT WITH EYES AND SKIN. Wash thoroughly after use. Close container after each use.

FIRST AID: EYE CONTACT: Flush thoroughly with water for at least 15 minutes. If irritation persists, get medical attention. IF INHALED: If affected by vapor or spray mist, move to fresh air. If breathing difficulty continues, get medical attention. IF SWALLOWED: Drink 2 glasses of water. Get medical attention immediately.

DO NOT TAKE INTERNALLY. KEEP OUT OF REACH OF CHILDREN. For additional safety and chronic health hazard information, refer to the Material Safety Data Sheet for this product.

EMERGENCY MEDICAL TELEPHONE: 1-888-345-5732

This product contains less than 50 g/L VOC

WARNING! If you scrape, sand or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH-approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead.

The data on this sheet represents typical values. Since application variables are a major factor in product performance, this information should serve only as a general guide. Valspar assumes no obligation or liability for use of this information. UNLESS VALSPAR AGREES OTHERWISE IN WRITING, VALSPAR MAKES NO WARRANTIES, EXPRESS OR IMPLIED, AND DISCLAIMS ALL IMPLIED WARRANTIES INCLUDING WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR FREEDOM FROM PATENT INFRINGEMENT. VALSPAR WILL NOT BE LIABLE FOR ANY SPECIAL, INCIDENTAL OR CONSEQUENTIAL DAMAGES. Your only remedy for any defect in this product, is the replacement of the defective product, or a refund of its purchase price, at our option.

