

INSTRUCTIONS:

Slip ring over 60CM18 boot until it makes contact with ridge around boot.



Wiring Device-Kellems
Hubbell Incorporated (Delaware)
185 Plains Road
Milford, CT 06460-8897
(203) 882-4800

PD1559

PRINTED IN U.S.A.

6/98

