



PUSH-IN WIRE CONNECTORS (FOR SOLID OR STRANDED COPPER WIRES)




- Large wire range: accommodates 22-12 AWG solid or stranded copper wire
- Fast, safe and reliable installation saves time and money
- No twisting or taping of conductors required
- Just strip the wire, insert the connector and you are done
- One wire per opening ensures loose connections are eliminated
- Made of strong, UL 94V-2 flame retardant polycarbonate
- Rated 600 volts (up to 1,000 volts for fixtures and signs)
- Temperature range from -40°F to 221°F (-30°C to 105°C)
- Integrated test port enables continuity testing
- Color coded for easy identification
- Compact design perfect for tight spaces

CATALOG NO.	UPC CODE	COLOR CODE	NO. OF WIRES	PACKAGING		WEIGHT LBS./CTN.
				UNIT	CARTON	
PIWC-2-C	14211	yellow	2	box of 100	4,500 (45 boxes of 100)	29
PIWC-2-B	14221	yellow	2	bag of 500	7,000 (14 bags of 500)	39
PIWC-3-C	14212	orange	3	box of 100	4,500 (45 boxes of 100)	38
PIWC-3-B	14222	orange	3	bag of 500	5,500 (11 bags of 500)	42
PIWC-4-C	14213	clear	4	box of 75	3,375 (45 boxes of 75)	37
PIWC-4-B	14223	clear	4	bag of 400	4,400 (11 bags of 400)	42
PIWC-5-C	14214	blue	5	box of 50	2,250 (45 boxes of 50)	30
PIWC-5-B	14224	blue	5	bag of 300	3,600 (12 bags of 300)	42
PIWC-6-C	14326	purple	6	box of 50	2,250 (45 boxes of 50)	35
PIWC-6-B	14327	purple	6	bag of 250	3,000 (12 bags of 250)	41
PIWC-8-C	14215	grey	8	box of 40	1,800 (45 boxes of 40)	36
PIWC-8-B	14225	grey	8	bag of 200	2,400 (12 bags of 200)	44


INSTALLATION



TURN OFF POWER.
Strip wire approximately 0.45 inches (11mm).



Push the stripped conductor into the port of connector fully. No more twisting or taping.



Use a voltage meter to test your connection via the port on connector.