

viiega



691514268057



**Viiega MegaPress Press-In
Branch Connector, Carbon steel,
Model 4812.2**

for d	FPT
2	3/4

Part No
26805

viiega



691514268156



**Viiega MegaPress Press-In
Branch Connector, Carbon steel,
Model 4812.2**

for d	FPT
3	3/4

Part No
26815

viiega



691514268200



**Viiega MegaPress Press-In
Branch Connector, Carbon steel,
Model 4812.2**

for d	FPT
4	3/4

Part No
26820

viiega



691514268255



**Viiega MegaPress Press-In
Branch Connector, Carbon steel,
Model 4812.2**

for d	FPT
6	3/4

Part No
26825

viiega



691514268002



**Viiega MegaPress Press-In
Branch Connector, Carbon steel,
Model 4812.2**

for d	FPT
1 1/2	3/4

Part No
26800

viiega



691514268101



**Viiega MegaPress Press-In
Branch Connector, Carbon steel,
Model 4812.2**

for d	FPT
2 1/2	3/4

Part No
26810

viiega



691514268354



**Viiega MegaPress Press-In
Branch Connector, Carbon steel,
Model 4812.25**

for d	FPT
2	3/4

Part No
26835

viiega



691514268453



**Viiega MegaPress Press-In
Branch Connector, Carbon steel,
Model 4812.25**

for d	FPT
3	3/4

Part No
26845

viiega



691514268507



**Viiega MegaPress Press-In
Branch Connector, Carbon steel,
Model 4812.25**

for d	FPT
4	3/4

Part No
26850

viiega



691514268552



**Viiega MegaPress Press-In
Branch Connector, Carbon steel,
Model 4812.25**

for d	FPT
6	3/4

Part No
26855

viega



691514268309



**Viega MegaPress Press-In
Branch Connector, Carbon steel,
Model 4812.25**

for d	FPT
1½	¾

Part No
26830

viega



691514268408



**Viega MegaPress Press-In
Branch Connector, Carbon steel,
Model 4812.25**

for d	FPT
2½	¾

Part No
26840

viega



691514268651



**Viega MegaPress Press-In
Branch Connector, Carbon steel,
Model 4812.3**

for d	FPT
2	¾

Part No
26865

viega



691514268750



**Viega MegaPress Press-In
Branch Connector, Carbon steel,
Model 4812.3**

for d	FPT
3	¾

Part No
26875

viega



691514268804



**Viega MegaPress Press-In
Branch Connector, Carbon steel,
Model 4812.3**

for d	FPT
4	¾

Part No
26880

viega



691514268859



**Viega MegaPress Press-In
Branch Connector, Carbon steel,
Model 4812.3**

for d	FPT
6	¾

Part No
26885

viega



691514268606



**Viega MegaPress Press-In
Branch Connector, Carbon steel,
Model 4812.3**

for d	FPT
1½	¾

Part No
26860

viega



691514268705



**Viega MegaPress Press-In
Branch Connector, Carbon steel,
Model 4812.3**

for d	FPT
2½	¾

Part No
26870

viega



691514268958



**Viega MegaPress Press-In
Branch Connector, Carbon steel,
Model 4812.35**

for d	FPT
2	¾

Part No
26895

viega



691514269054



**Viega MegaPress Press-In
Branch Connector, Carbon steel,
Model 4812.35**

for d	FPT
3	¾

Part No
26905

viEGA



6 9 1 5 1 4 2 6 9 1 0 8



Viega MegaPress Press-In Branch Connector, Carbon steel, Model 4812.35

for d	FPT
4	3/4

Part No
26910

viEGA



6 9 1 5 1 4 2 6 9 1 5 3



Viega MegaPress Press-In Branch Connector, Carbon steel, Model 4812.35

for d	FPT
6	3/4

Part No
26915

viEGA



6 9 1 5 1 4 2 6 8 9 0 3



Viega MegaPress Press-In Branch Connector, Carbon steel, Model 4812.35

for d	FPT
1 1/2	3/4

Part No
26890

viEGA



6 9 1 5 1 4 2 6 9 0 0 9



Viega MegaPress Press-In Branch Connector, Carbon steel, Model 4812.35

for d	FPT
2 1/2	3/4

Part No
26900

viEGA



6 9 1 5 1 4 2 6 9 2 0 7



Press-In Branch Connector tool kit, Model 4878.5

for d
1 1/2 - 4, 6

Part No
26920

viEGA



6 9 1 5 1 4 2 6 9 6 5 8




Press-In Branch Connector pilot bit, Steel, Model 4879

Part No
26965

viEGA




6 9 1 5 1 4 2 6 8 3 7 8



Press-In Branch Connector adapter, HEX, Steel, Model 4812.28

Part No
26837

viEGA




Press-In Branch Connector positioning guide, Stainless steel, Model 4278.6

for d
2

Part No
746 025


viEGA



Press-In Branch Connector positioning guide, Stainless steel, Model 4278.6

Part No
746 049

viEGA



Press-In Branch Connector positioning guide, Stainless steel, Model 4278.6

for d
4


Part No
746 452

for d
3

viega



Press-In Branch Connector positioning guide, Stainless steel, Model 4278.6



for d


6

Part No
746 476

viega



Press-In Branch Connector positioning guide, Stainless steel, Model 4278.6



for d


2½

Part No
746 032

viega



Press-In Branch Connector positioning guide, Stainless steel, Model 4278.6



for d

1½

Part No
746 353

viega



Press-In Branch Connector adapter, SDS-plus drive, Steel, Model 4878.91



6 9 1 5 1 4 2 6 9 5 5 9

Part No
26955

viega



Press-In Branch Connector tool, Steel, Model 4878.9



for d

1½

Part No
26925

viega



Press-In Branch Connector bolt, Steel, Model 4878.92



6 9 1 5 1 4 2 6 9 6 0 3

Part No
26960