



GLOSS AND HARDNESS CATALYST V705

Features

- Speeds Drying

General Description

Alkyd Gloss and Hardness Catalyst speeds drying while producing a higher gloss and more corrosion resistance, as well as a harder enamel finish. Other benefits include increased solvent and chemical resistance.

Recommended For

Corotech® Gloss & Hardness Alkyd Catalyst can be used with the following Corotech® Alkyds:
V200 Line, V201 Line, V220 Line, V230 Line and V231 Line.

Limitations

Product Information		
Colors — Standard: N/A — Tint Bases: N/A — Special Colors: N/A	Technical Data	Gloss & Hardness Catalyst
	Generic Type	Isocyanate
	Pigment Type	N/A
Certification: The product supported by this data sheet contains a maximum of 615 grams per liter VOC / VOS (5.13 lbs. /gal.) excluding water & exempt solvents. This product is considered a paint additive and is therefore not regulated by Ozone Transport Commission (OTC) regulations.	Volume Solids (mixed as recommended)	69.1% ± 1.0% mixed
	Coverage per Gallon at Recommended Film Thickness	N/A
	Recommended Film Thickness	N/A
	Recommended — Wet	N/A
	Film Thickness — Dry	N/A
	Depending on surface texture and porosity. Be sure to estimate the right amount of paint for the job. This will ensure color uniformity and minimize the disposal of excess paint.	
	Dry Time @ 77°F	N/A
	— To Touch	N/A
	— To Recoat	N/A
	*If top coat is not applied within 72 hours abrade the surface to ensure proper inter-coat adhesion. Maximum abrasion and chemical resistance are achieved at full cure; care should be taken to prevent damage to the coating during the curing process. High humidity and cool temperatures will result in longer dry, recoat and cure times.	
Technical Assistance: Available through your local authorized independent Benjamin Moore® retailer. For the location of the retailer nearest you, call 1-800-225-5554, or visit www.benjaminmoore.com	Dries By	N/A
	Dry Heat Resistance	N/A
	Viscosity @ 77°F (mixed as recommended)	N/A
	Flash Point (Mixed)	91° F. (TT-P-141, Method 4293)
	Gloss/Sheen	N/A
	Surface Temperature	N/A
	— Min.	N/A
	at application	N/A
	— Max.	N/A
	Surface must be dry and at least 5° above the dew point	
	Thin With	N/A
	Clean Up Thinner	Xylene
	Mixed Ratio (by volume)	See Application Section
	Induction time @ 77°F	None
	Pot Life @ 70°F	2 – 3 Hours
	Weight Per Gallon (mixed as recommended)	9.0 lbs.
	Storage	40°F
	— Min.	95°F
	Temperature	— Max.
	Volatile Organic Compounds (VOC) 615 Grams / Liter 5.13 LBS / Gallon	

Gloss And Hardness Catalyst V705

WARNING! If you scrape, sand, or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead.

Application

Mix the product thoroughly before adding to the alkyd enamel. Add a maximum of 1 pint per gallon of paint. When working with Isocyanates it is recommended that you wear an appropriate, properly fitted respirator approved by NIOSH/MSHA; an airline respirator (TC19C NIOSH/MSHA) is recommended.

Environmental Health & Safety Information

DANGER!

Harmful if inhaled

Causes skin irritation

Causes serious eye irritation

May cause allergy or asthma symptoms or breathing difficulties if inhaled

May cause an allergic skin reaction

Suspected of causing cancer

May cause respiratory irritation

May cause damage to organs through prolonged or repeated exposure

May be fatal if swallowed and enters airways

Flammable liquid and vapor

Prevention: Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Use personal protective equipment as required. Use only outdoors or in a well-ventilated area. Wash face, hands and any exposed skin thoroughly after handling. In case of inadequate ventilation wear respiratory protection. Contaminated work clothing should not be allowed out of the workplace. Do not breathe dust/fume/mist/vapors/spray. Keep away from heat/sparks/open flames/hot surfaces, no smoking. Keep container tightly closed. Ground/bond container and receiving equipment. Use explosion-proof electrical/ventilating/lighting/equipment. Use only non-sparking tools. Take precautionary measures against static discharge. Keep cool. Wear protective gloves/protective clothing/eye protection/face protection.

Response: If exposed or concerned get medical attention. If in eyes rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists get medical attention. If skin irritation or rash occurs get medical attention. If on skin (or hair) take off immediately all contaminated clothing. Rinse skin with water. Wash contaminated clothing before reuse. If inhaled remove victim to fresh air and keep at rest in a position comfortable for breathing. If experiencing respiratory symptoms: Call a POISON CENTER or physician. If swallowed immediately call a POISON CENTER or physician. Do NOT induce vomiting. In case of fire use CO₂, dry chemical, or foam for extinction.

Storage: Store locked up. Store in a well-ventilated place. Keep container tightly closed.

Disposal

Dispose of contents/container to an approved waste disposal plant.

IMPORTANT: Designed to be mixed with other components. Mixture will have hazards of all components. Before opening packages, read all warning labels. Follow all precautions.

WARNING: This product contains a chemical known to the state of California to cause cancer and birth defects, or other reproductive harm.

KEEP OUT OF REACH OF CHILDREN

Refer to Safety Data Sheet for additional health and safety information.