

GENERAL DESCRIPTION

Valspar Premium Clear Coating Kit is a waterbased two-component epoxy that provides a coating 2X stronger than concrete for the toughest floor in one coat. This extreme epoxy formula is fortified with advanced bonding technology to provide superior adhesion and durability. It beautifies and protects with a durable glossy finish that protects against damage from hot tires, gasoline, oil and wear and tear.

PRODUCT FEATURES

- Semi-gloss
- · Advanced Bonding Technology
- · Anti-peel protection
- No hot-tire pickup

RECOMMENDED USES

- · Garage floors
- Interior concrete floors
- Top coat over Garage Floor Coating
- Top coat over interior Etching Stain
- . Do not use over surfaces treated with water repellent sealers

PACKAGING

Packaging: Kit

THINNING

Do not thin.

CLEANUP

Clean up with warm, soapy water.

STORAGE AND DISPOSAL

Do not freeze! Keep container closed when not in use. Do not transfer contents to other containers for storage or disposal. In case of spillage, absorb with inert material such as sand or kitty litter. Dispose of contaminated absorbent, container and/or unused contents in accordance with local, state and federal regulations.

COMPOSITION

Package

Fill

(oz./gal.)

Clear 128

PRODUCT SPECIFICATIONS

Vehicle Type: Epoxy

Recommended Film Thickness: 3.0 mil Wet 1.5 mil Dry

Viscosity: 90-120 KU

Gloss: 35-65 Units @ 60° angle

Flashpoint: 200°F

VOC (g/L): Less than 250 g/L mixed coating

Volume Solids: 53% Weight Solids: 62%

Weight Per Gallon: 10 lbs. /gal.

Practical Coverage:

Approx. 400 sq. ft. /gal. over smooth

concrete surfaces

Dry Time @ 77 °F and 50% Relative Humidity

To The Touch: 8 – 12 hours

Recoat: 24 hours

Full Cure: 72 hours for automobiles Application Temperature – 50-90 °F

<u>SURFACE PREPARATION</u>

READ INSTRUCTION SHEET FOR DETAILED SURFACE PREPARATION INSTRUCTIONS

General: All surfaces must be clean, dry and free of all loose, peeling paint or contaminants.

Bare Concrete: Allow 60 days minimum for new concrete to cure before sealing. Clean and etch new or bare concrete with Fast Prep™ Cleaner. Degreaser & Etcher. Follow all Fast Prep label instructions.

For Topcoating Etching Stain

Remove all residue and clean per Etching Stain label instructions. Allow the floor to dry completely, at least 24 hours. Additional dry time may be needed in cooler temperatures or higher humidity.

For Topcoating Garage Epoxy

Allow 24 hours for garage epoxy to cure. Additional dry time may be needed in cooler temperatures or higher humidity. For best results apply Valspar Premium Clear Coating after 24 hours and before 5 days. Remove all dirt, dust and debris from floor.

MIXING INSTRUCTIONS

READ INSTRUCTION SHEET FOR DETAILED MIXING INSTRUCTIONS

Open both cans of the epoxy kit and pour Part B Hardener into Part A Base. Stir the coating manually for 3 minutes, then cover and allow to stand for 15 minutes, out of direct sunlight. Stir the mixture for one minute immediately before application. Painted surfaces may become slippery when wet; use of the anti-skid additive is highly recommended. Stir anti-skid additive into the mixture for one minute just prior to application.

APPLICATION

READ INSTRUCTION SHEET FOR DETAILED **APPLICATION INSTRUCTIONS**

Start with a 2-3" polyester brush and paint a 2" strip along the edges. Be sure to paint into joints, corners and any other hard-to-reach areas. Use a premium-quality, medium nap (3/8") roller for the rest of the garage. Spread the paint uniformly, finishing with long, even strokes. The epoxy will apply a milky white color but will dry to



Premium Clear Coating Kit 81052 series

a clear finish. Working in 4' x 4' sections, apply the epoxy in one direction, then roll it again in a second direction, perpendicular to the first. Clean hands, tools, drips and spills with warm, soapy water.

LEAD WARNING

WARNING! If you scrape, sand or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH-approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead.

LIMITED WARRANTY

The data on this sheet represents typical values. Since application variables are a major factor in product performance, this information should serve only as a general guide. Valspar assumes no obligation or liability for use of this information. **UNLESS VALSPAR AGREES OTHERWISE IN** WRITING, VALSPAR MAKES NO WARRANTIES, EXPRESS OR IMPLIED, AND **DISCLAIMS ALL IMPLIED WARRANTIES INCLUDING WARRANTIES OF** MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR FREEDOM FROM PATENT INFRINGEMENT. VALSPAR WILL NOT BE LIABLE FOR ANY SPECIAL, INCIDENTAL OR CONSEQUENTIAL **DAMAGES.** Your only remedy for any defect in this product, is the replacement of the defective product, or a refund of its purchase price, at our option.

CAUTIONS

DANGER!

THIS KIT CONTAINS THE FOLLOWING CHEMICALS THAT MAY BE HARMFUL IF MISUSED: EPOXY RESINS, GLYCOL ETHERS AND AMINES. READ CAUTIONS ON INDIVIDUAL CONTAINERS CAREFULLY. KEEP OUT OF REACH OF CHILDREN

For additional safety and chronic health hazard information, refer to the Material Safety Data Sheet for this product.

EMERGENCY MEDICAL TELEPHONE: 1-888-345-5732

When Parts A and B are mixed together, this epoxy coating contains less than 250 g/L VOC.

> 1191 Wheeling Road, Wheeling, IL 60090 888.313.5569 www.valsparpaint.com Revised: Sept 2012