



AERATION FAN MOTOR

CUSTOMER IS RESPONSIBLE FOR DETERMINING THAT MOTOR PERFORMANCE IS SUITABLE IN THE APPLICATION.

REV. DESC: LEAD HOLE .88 DIA WAS LEAD HOLE .88 DIA. W/PLUG		
REV. LTR: A	VERSION: 01	TDR: 00000444235
8061A792	FILE: \AAA\00110\931	REVISED: 21:15:40 09/24/2007
	MTL: -	BY: ENMARHO

BALDOR ELECTRIC Co.

HOR 143-5T TEAO 35M-T.P/AERA FAN, 2 POLE "W" BASE(35BA4009)

35LYT908