



CUSTOMER IS RESPONSIBLE FOR DETERMINING THAT BALDOR'S PRODUCT WILL PERFORM SUITABLY IN THE INTENDED APPLICATION.

REV. DESC: CORRECT LEADER TO SAY 5.88 DIA B.C.		
REV. LTR: A	VERSION: 01	TDR: 00000778254
FILE: \AAA\00173\887	REVISED: 01: 44:13 12/18/2012	
MTL: -	BY: ENJESMO	

BALDOR

STD HORZ 143-5TC TEFC 35M W/ 1.09 DIA. LEAD HOLE

SH 1 of 1

35LYAA002