


NOTE:

1. Move Burrs R0.005MAX
2. The concentricity with thread within 0.01in
3. Parts to be free of dirt and chips

| | | | | | | | | | |
|--|-----|------|----------|---|--|---------|---|-------------|-------|
| "This drawing contains proprietary and confidential information of Midland Metal Mfg., Co. and shall not be reproduced, copied, loaned, or submitted to outside parties for examination without our consent" | | | | Date: | | UNIT: | INCH | Material: | |
| | | | | Drawn: | | Scale: | 1=1 | Part Title: | |
| 4 | | | | Checked: | | PROJECT |  | PART NO. | 32089 |
| 3 | | | | Approved: | | | | | |
| 2 | | | | MIDLAND METAL MFG. CO. KANSAS CITY, MO | | | | DWG. NO. | |
| 1 | | | | | | | | | |
| NO. | PCA | Date | Revision | TOLERANCES ARE: DECIMALS. .X:±0.03 .XX:±0.01 .XXX:±0.005 ANGLES:±1° FRACTIONS ± 1/8 | | | | | |